

---

Sun, May 3<sup>rd</sup> Go Riteway – Shuttle Service - 800-236-5450 / 414-570-5200 from the airport.  
Best Western / Excel Grand Hotel, 2840 N Grandview Park Blvd, Pewaukee, WI, (262) 524-9300

---

Mon, May 4<sup>th</sup> **WEAR YOUR WORK CLOTHES**

- 5:30 am Breakfast @ Hotel
- 6:00 am Depart for Spancrete Valders Plant – Via Motor Coach
- 8:00 am Tour/Observation of Hollowcore Operations - 48” & 96” Floor Slab Production
- 10:30 am Product Issues @ Valders Training Center – ED  
Round table discussions
- Manufacturers Handbook / Parts Manuals on CD
  - SMA Overview Videos (PC, CD & Projector)
    1. STRESSING PROCEDURE
    2. TEST CYLINDER
    3. DETENSIONING/SAWING
    4. STRIPPING/YARDING/SHIPPING
    5. ERECTION PROCEDURE
- 12:00 am Lunch - @ Mr. Luckys
- 1:00 pm Tour of Wetcast Production Facility  
Tour yard, hollowcore production, batch plant operation
- 3:30 pm Departure for Hotel – Dinner on the way
- 5:00 pm Dinner @ Fridays at Miller Park
- 

Tue, May 5<sup>th</sup> **WEAR YOUR WORK CLOTHES**

- 6:45 am Breakfast @ Hotel
- 7:00 am Depart for Machine Shop - Via Multiple Vehicles
- 8:00 am Hands-on Multiple Stations - Demonstrations – @ Spancrete Global Services - Waukesha
- Machine Adjustments
  - Oscillator Timing & Set-up
  - Bushing replacement
  - Hydraulic System review with Price Engineering Representative
  - Website Forum
  - Bridgesaw Software
  - R & D Projects
- 11:30 am Lunch - @ Machine Shed / Departures
- 1:00 pm Hands-on Demonstrations Continued / Jobsite “Drive-by” – To Be Determined
- 3:30 pm Depart Plant & Clean-Up @ Hotel
- 6:00 pm Dinner @ Gasthaus (Optional)
- 

Wed, May 6<sup>th</sup> Departures

Ed Gross cell 414-467-0517 – Brian Schmidt cell 414-397-0106 – Nick Passint cell 414-531-2243